

## State of Utah **DEPARTMENT OF NATURAL RESOURCES** Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

## **Inspection Report Minerals Regulatory Program** May 29, 2008

Reviewed SW

Mine Name: Eureka Rock	Permit Number: S0230094
Operator Name: Eureka Rock LLC	Inspection Date: March 13, 2008
Inspector(s): L Heppler, T Munson	<b>Time</b> : 1:00 am
Other Participants: None	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	$\boxtimes$	$\boxtimes$	
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls,			
8. Soils		$\boxtimes$	
9. Revegetation			

Bond Renewal Date: 12-20-2009 Bond Amount: \$15,300 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Every effort should be made to salvage topsoil from the site prior to mining or constuction.

Photos were taken to document site conditions.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:pb

cc: Ben McInnes Attach - GIS File Name and Path Inspection March 13, 2008 Page 2 of 2 M/023/0094

